


This diagram illustrates a mechanical assembly, possibly a printer or copier, showing various components and their movement. The assembly includes a large cylindrical component (14) at the bottom, a series of rollers (16, 18, 20, 22, 24, 26) and a belt (12) in the center, and a complex mechanism at the top. Arrows indicate the direction of movement for several parts. Reference numerals 10, 12, 14, 16, 18, 20, 22, 24, 26, 87, and 88 are used to identify specific components and features.

2/7

FIG. 2



3/7

FIG. 6







FIG. 3




4/7





6/7



7/7



FIG. 8

